

APX P25 Interfaced DVR/VRX1000 Firmware Release 1.43 – Release Notes

DVR/VRX Application Software (4C083X11): New Version: **1.43**; Old Version: 1.42

DVR/VRX BB DSP (4C083x04): Version: **1.42** (unchanged)

DVR TR DSP (4C083x03): Version: **1.18** (unchanged)

VRX TR DSP (4C087x05): Version: **1.07** (unchanged)

Tweaker Software (6A083X05): Version: **1.17** (unchanged)

Note: New firmware and Tweaker software is supporting both hardware platforms - VRX1000 and DVR.

Compatible with following Motorola Radio Firmware Versions:

APX2500/4000/4500/5500/6000/6500/7000/7500/8000/8500: R19.00.00

New Features / Enhancements:

- None

Issues fixed in this release:

- If MSU initiates emergency call while operating on TDMA system, Local PSU may fail to display properly emergency ergonomics of the received emergency call
- While MSU is operating on Type II system and digital voice channel , DVR may unnecessarily transmit patch control TSBKs to Local PSUs
- When Unit ID translation is enabled on DVR digital channel, multiple DVRs may attempt to handle inbound / outbound calls and emergency alarm from Local PSU.

Known issues in Firmware Release 1.43:

- None.