

PDR8000 Release 4.00

Product Tested:

Repeater Module Firmware: 4C088X01 R4.00

Repeater Module Boot Firmware: 4C088X02 R4.00

Transceiver DSP: 4C083X03 R1.18

Baseband DSP: 4C083X04 R1.51

IF Module Firmware: 4C088X05 R4.00

IF Module Boot Firmware: 4C088X06 R4.00

Tweaker Programming Software: 6V088X01 R4.00

Tested With:

PSU Type: APX7000 **PSU Firmware:** D15.71.55

Modems: Motorola UDS V.3225, Raymar-Telenetics V3600

GCM 8000 Comparator: CvCM_R07.17.005

MLC AGU: R060027

New Features/Performance Enhancements:

Description: The following features had been added and/or improved in Release 4.00. This release contains fixes list in Issues fixed in this release.

FEATURE	DESCRIPTION		
Booster Pack	50-Watt VHF, UHF, 700 MHz & 800 MHz Transmit Boosters to work with		
Suitcase	all PDR8000® with firmware R4.0 and above		
PDR8000 Keypad	Security option to restrict access to PDR8000 Keypad/Display		
Lockout	functionality via password protection		
PDR8000 External	Provides operational status indication to user with PDR8000 R4.0		
Status LED	suitcase closed		
Variable Fan Control	Reduction of fan activity at lower temperatures; power/noise/wear		
	reductions for Booster Pack and PDR8000 R4.0		
Maintain PDR Error	Maintain PDR Error Logs through Power Interruption; Increases		
Logs	maintainability & serviceability for all PDR8000 with R4.0 firmware		

2019-09-23 Page 1 of 2



Issues Fixed since last major Release:

Issue	DESCRIPTION	Release	Date
V.24 with IP link	Better management of delayed voice frames on V.24 when converting to IP wide area network	R4.0	2019-09-23

Known PDR8000 Issues in this Release:

Issue	DESCRIPTION

Known PDR8000 Limitations:

None



Subscribe to our newsletter if you want to be informed about new releases and updates. Please visit http://futurecom.com/support/newsletter/

2019-09-23 Page 2 of 2