

XTL DVR Software – Release 3.42

DVR Application Software – New Version: 3.42; Old version 3.41

BB DSP: Version: 1.20 (unchanged) **TR DSP**: Version: 1.15 (unchanged)

Tweaker Software: Version: 3.45 (unchanged)

Requires XTL5000 / XTL2500 Firmware Listed Below:

Host: R20.00.10A DSP: R19.50.00 UCM R05.07.15 MCH: R16.00.00 CPS: R20.00.00 MACE: R07.11.12

New Features / Performance Enhancements:

Display DVR Serial Number in MSU Test Mode - while in MSU Test Mode DVR Serial Number info is interleaved with DVR Application Software version number.

Issues fixed in this release:

 Affected configuration: MSU on P25 trunking system, DVR on digital channel, PSUs on DVRS enabled channel - DVR is not terminating properly inbound call from distant PSU when nearby PSU turns off or changes channel (sends deregistration request).

Known DVR issues in Firmware Release 3.42:

None.

June 2014 Page 1 of 1